

HABS
ORE
IS-MED,
1-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Medford Service Center
1319 McAndrews Road
Medford
Jackson County
Oregon

HABS No. OR-160

Natalie Brown, Photographer

April 1993

- OR-160-1 VIEW OF MEDFORD SERVICE CENTER AT CORNER OF McANDREWS ROAD (R.)
AND POPLAR DRIVE (L.), FACING NORTHEAST.
- OR-160-2 VIEW OF MEDFORD SERVICE CENTER, INTERIOR OF COMPOUND SHOWING
BUILDINGS #2301, #2500, AND #2205 (L. TO R.), FACING SOUTHEAST.
- OR-160-3 VIEW OF MEDFORD SERVICE CENTER, INTERIOR OF COMPOUND SHOWING
BUILDINGS #2301, #2205, #2500, #2202, AND #2300 (L. TO R.),
FACING SOUTHWEST.

Note: All photographs are 8" x 10" enlargements from 4" x 5" negatives.